



FOOTPLATE

NEW SOUTH WALES BRANCH / LOCOMOTIVE DIVISION

ISSUE 27: JULY 2017

Update: Asbestos in C and K Sets

The Sydney Trains WHS Divisional Committee has advised the Locomotive Division that the following C and K sets have been tested and verified safe to re-enter service by an external independent Hygienist.

Date Verified Safe: 15/07/2017

C1	C3	C6	C8
C9	C10	K63	K71

Date Verified Safe: 17/07/2017

K65	K75	K79	K83	K72
K82	C12	C14	K86	K81

These sets have undergone additional testing at the request of HSRs. This testing was performed by external independent Hygienist WSP with a process and methodology verified by SafeWork NSW.

HSRs have scrutinised the results and reports for each individual unit and are satisfied that the above sets are safe. Sydney Trains will continue to have each unit tested in this manner prior to them re-entering service.

Your Union will continue to work with HSRs and advise Members which sets have been through the agreed process to ensure Member safety.

If you have any concerns please contact your local HSR or the Locomotive Division.